

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN
Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representativ	es Present During the Inspection:
Company	Charles Reynolds
OGM	Steve Demczak

# Inspection Report

Permit Number:	C0070011			
Inspection Type:	PARTIAL			
Inspection Date:	Wednesday, October 13, 2010			
Start Date/Time:	10/13/2010 2:00:00 PM			
End Date/Time:	10/13/2010 4:00:00 PM			
Last Inspection:	Monday, September 20, 2010			

Inspector: Steve Demczak,

Weather: Sunny, 60's

InspectionID Report Number: 2527

Accepted by: jhelfric

11/2/2010

Permitee: HIAWATHA COAL CO INC Operator: HIAWATHA COAL CO INC

Site: HIAWATHA MINE

Address: PO BOX 1240, HUNTINGTON UT 84528

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

<b>Total Permitted</b>	12,177.00	
<b>Total Disturbed</b>	290.00	
Phase I	95.90	
Phase II		
Phase III		

Mineral Ownership Types of Operations

✓ Federal
✓ Underground

✓ State
Surface

County
Loadout

✓ Fee
Processing

Other
Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

Inspector's Signature:

Steve Demozak,

Date

Monday, October 18, 2010

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Wednesday, October 13, 2010

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>✓</b>		<b>~</b>	
3.	Topsoil	<b>~</b>		<b>V</b>	
4.a	Hydrologic Balance: Diversions	<b>✓</b>		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>✓</b>		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		<b>✓</b>	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	<b>V</b>		<b>V</b>	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	<b>V</b>		<b>✓</b>	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations	<b>V</b>		<b>✓</b>	
16.a	Roads: Construction, Maintenance, Surfacing	<b>V</b>		<b>V</b>	
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	<b>V</b>		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070011 Inspection Type: PARTIAL

Inspection Date: Wednesday, October 13, 2010

Page 3 of 3

#### 2. Signs and Markers

The idientification signs are next to the roads to the mine site.

## 3. Topsoil

Topsoil piles were inspected with no signs of erosion.

## 4.a Hydrologic Balance: Diversions

The diversions were spot-checked and would function during a storm event.

## 4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment ponds contained little to no water. It is unlikely that they will discharge in the near future. No hazardous conditions were noticed during the inspection.

# 7. Coal Mine Waste, Refuse Piles, Impoundments

The site is inactive. The slurry piles have not been mined for several months.

## 10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

## 12. Backfilling And Grading

No reclamation is taking place at Hiawatha.

## 15. Cessation of Operations

The company has submitted a letter to the Division that it's Hiawatha operation is in Temporary in Cessation.

# 16.a Roads: Construction, Maintenance, Surfacing

The road to Middle Fork is falling apart. The asphalt is breaking up.

## 18. Support Facilities, Utility Installations

No new support facilities were constructed.